

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
Company	Kenneth S. Fleck Manager of Geology and Environ				
OGM	Karl Houskeener, Environmental Scientist III				

Inspection Report

Permit Number:	C0150018			
Inspection Type:	PARTIAL			
Inspection Date:	Tuesday, October 20, 2009			
Start Date/Time:	10/20/2009 8:30:00 AM			
End Date/Time:	10/20/2009 12:30:00 PM			
Last Inspection:	Tuesday, September 22, 2009			

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Overcast/Light Rain, Temp. 45 Deg. F.

InspectionID Report Number: 2163

Accepted by: jhelfric

10/29/2009

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: DEER CREEK MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: **EMERY**

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Total Permitted	19,740.78	
Total Disturbed	98.05	
Phase I	0.60	
Phase II		
Phase III		

Current Acreages

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground ☐ Surface State Loadout County Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl Houskeeper, Environmental Scientist III

Date

Tuesday, October 20, 2009

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Inspection Type: PARTIAL

Inspection Date: Tuesday, October 20, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓			
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150018 Inspection Type: PARTIAL

Inspection Date: Tuesday, October 20, 2009

Page 3 of 3

2. Signs and Markers

The ID signs located at the points of public access to the permit area contained the necessary information.

4.a Hydrologic Balance: Diversions

The water bars on the main fan access road have been re-established.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond located at the mine site is being cleaned. An access ramp is being used to extend the reach of the track hoe. The ramp will be removed as part of the cleaning process. Material from the sediment pond cleaning is being hauled to the waste rock site.